



| ITEM | Q/S | PART NO. | QTY | DESCRIPTION | EST. WT. | PAINT CODE |
|-------|-----|---------------|-----|-----------------------------|----------|------------|
| ** 1 | B | 50-80-0472-24 | 1 | LADDER STRINGER L.H. | | |
| ** 2 | B | 50-80-0472-25 | 1 | LADDER STRINGER R.H. | | |
| ** 3 | B | 17-04-8022-00 | 8 | LADDER RUNG ANGLE | | |
| ** 4 | A | 50-80-0472-26 | 2 | LADDER STRINGER SPLICE | | |
| ** 5 | B | 10-29-0139-00 | 2 | LADDER STRUT | | |
| ** 6 | A | 10-29-0141-00 | 2 | LADDER STRUT | | |
| * 7 | A | 10-29-0142-00 | 1 | ANCHOR LADDER FOOT | | |
| * 8 | A | 10-29-0140-01 | 2 | CLIP INSIDE LADDER | | |
| ** 9 | - | 10-09-0314-17 | 3 | 1/2X2 LG SQ HD BOLT HDG | | |
| ** 10 | - | 10-09-0314-14 | 25 | 1/2X1-1/4 LG SQ HD BOLT HDG | | |
| ** 11 | - | 10-09-0316-03 | 28 | 1/2 HEX NUT HDG | | |

* THESE QTY'S SHOWN ARE FOR (1) COMPLETE LADDER.
 ** THESE QTY'S SHOWN ARE FOR (1) 8'-0" LG LADDER SECTIONS.

| MODEL * | LADDER HT | * OF SECTIONS |
|---------------|-----------|---------------|
| 10-03-0000-01 | 8' | 1 |
| -02 | 16' | 2 |
| -03 | 24' | 3 |
| -04 | 32' | 4 |
| -05 | 40' | 5 |
| -06 | 48' | 6 |
| -07 | 56' | 7 |
| -08 | 64' | 8 |
| -09 | 72' | 9 |
| -10 | 80' | 10 |
| -11 | 88' | 11 |
| -12 | 96' | 12 |
| -13 | 104' | 13 |
| -14 | 112' | 14 |
| -15 | 120' | 15 |

PTD W/ANGLE RUNGS
HDG BOLTS



INSIDE WALL LADDER ASSY

71561 B 10-03-0000-00/15

| | | | | | | |
|---|---|--------------------|-----|-----|---------|------------|
| CONFIDENTIAL THIS DRAWING IS THE PROPRIETARY PROPERTY OF COLUMBIAN TECTANK, AND SHALL NOT BE USED NOR REPRODUCED WITHOUT THE EXPRESS WRITTEN CONSENT OF THE CORPORATION. | D | | | | | NTS |
| | C | REMOVED PAINT CODE | JRP | MBB | 12-98 | BV 5/22/87 |
| | B | ADDED NEW BORDER | DKN | JBB | 5/8/98 | JP 5/26/87 |
| | A | REV. PART # ITEM 3 | JR | CE | 2/12/87 | KM 5/29/87 |